

**Mississippi State Penitentiary  
Parchman, Mississippi  
2017 Sanitation Inspection Report  
(June 05-08, 2017)**

**\*Note: Deficiencies highlighted in red are repeats since last inspection.**

<b>Facility Name &amp; Address:</b> Mississippi State Penitentiary Hwy. 49 West Parchman, Mississippi 38728	<b>Inspected By:</b>  Rayford Horton, Environmental Admin. I <hr/> INSTITUTIONAL SERVICES P.O. BOX 1700 JACKSON, MISSISSIPPI 39215-1700 PHONE 601/576-7693
<b>Environmental Sanitation</b>	<b>Date of Inspection: June 07, 2017</b>
<b>Deficiency</b>	<b>Attachments</b>
<b>Unit 29 Bldg. A / Zone A</b>	
Shower door frame is loose	
Cell 15 leaks water when it rains, screen has a hole and light does not work	(See Photo Page 73)
Cell 20 no mattress cover, hole in screen	
Cell 24 no pillow	
Cell 25 no mattress cover	
Cell 27 hole in screen	
Cell 28 no mattress	
Cell 30 no mattress cover	
Shower 1 & 3 no lights	
Cell 32 no mattress, hole in screen	
Cell 33 no mattress cover	
Upstairs water fountain cover missing	
Zone has lights out throughout the zone	(See Photo Page 79)
<b>Unit 29 Bldg. A / Zone B</b>	
Entrance area hole in tiles	
Water fountain needs a cover	
Cell 74 screen on door needs to be fixed	
No lights in top tier showers	
<b>Unit 29 Bldg. B / Zone A</b>	
Cell 22 hole in screen, no mattress cover	
Cell 23 no lights, no mattress cover	
Cell 26 no mattress cover	
Cell 27 no mattress	
Cell 28 no mattress cover, no pillow	
Cell 29 no mattress	
Cell 30, 31 & 38 no pillows	

Cell 37 no pillows, rusty sheets, no power	
No lights in top tier showers	
Cell 42 no lights, no hot water	
<b>Unit 29 Bldg. B / Zone B</b>	
Ceiling has exposed wires and lights out	(See Photo Page 75) (See Photo Page 76)
Water fountain needs a cover	
Water leaks through the wall	(See Photo Page 77)
Cell 53 sink is leaking, no power, no electricity, has a hole in the wall	
Cell 54 no electrical socket, no electricity, water leaks when it rains, no mattress nor pillow	
Exposed wires next to cells 53-56	(See Photo Page 74)
Cell 49 no beds, no mattress, no electricity	
Floor tile replacement on needed throughout the zone	
<b>Unit 29 Bldg. C / Zone A</b>	
Large hole in ceiling at hallway entrance	
Missing ceiling tiles	
2 <sup>nd</sup> urinal out of order	
1 <sup>st</sup> toilet is out of order	
Bed 52 no pillow	
2 <sup>nd</sup> toilet, 2 <sup>nd</sup> sink out of order	
No lights in showers, paint peeling	
Bed 63 no pillow	
<b>Unit 29 Bldg. C / Zone B</b>	
Pipe chase cover is off the wall	
Pipe chase in bathroom coming off the wall	
1 <sup>st</sup> toilet out of order	
Water fountain is out of order	
No lights in shower	
Sinks constantly running water	
The CTQ rooms will not lock	
Bed 93 and 94 has bird nest in window, holes in screens	(See Photo Page 78)
Shower 2 leaks, sink 2 continuously dripping	
Bed 94 no lights	
No lights in urinal area	
Numerous holes in window screen throughout zone	
Water fountain missing covers	
<b>Unit 29 Bldg. D / Zone A</b>	
Cell 2 needs a pillow, sheets	
Cell 4 needs a pillow	
1 <sup>st</sup> sink constantly dripping water	
Showers appears to have mold growing	

Showers constantly running downstairs	
Top water fountain missing cover and is out of order	
Sink 1 continuously running	
Sink 1 missing knob	
<b>Holes in the shower floor</b>	
Cell 29 sink is out of order	
Cell 30 needs mattress cover	
Cell 34 mattress torn	
Cell 36 no pillow	
Cell 38 no screen, no pillow, no mattress	
Cell 39 no screen	
Cell 40, 41, 42, 43, 46, 52, 53, 54 & 57 no pillow	
Cell 56, 57 no window screen	
Cell 59 no screen, no mattress	
<b>Unit 29 Bldg. D / Zone B</b>	
No lights above beds 78, 84 and 90, 94 and 96	
Birds are nesting above the entrance door	(See Photo Page 39)
One light missing above bed 86 and 88	
No light switch above bed 92	
<b>2<sup>nd</sup> urinal is out of order</b>	(See Photo Page 23)
1 knob missing on 2 <sup>nd</sup> sink	
Light out in upstairs shower	
Screen torn above bed 86	
19 lights out throughout building	
Screen missing above beds 90 and 118	
Hole in wall above beds 93 and 94	
<b>Bird nest in the Window</b>	(See Photo Page 24)
Bed 120 has no light socket	
Hole in screen above bed 119	(See Photo Page 25)
Water fountain does not work	
Roaches crawling on the floor	(See Photo Page 26)
Shower has mold in the ceiling	(See Photo Page 44)
<b>Unit 29 Bldg. E / Zone A</b>	
No lights above beds 1, 12, 16, 20, 44, and 46	
One light missing above bed 28	
Gap in under hang between beds 12 and 14	
Frame broken next to exit light	(See Photo Page 27)
Pipe chase cover missing	(See Photo Page 28)
Downstairs exist light not working	
Water leaks above bed 20 and no screen in window	
1 <sup>st</sup> shower has no hot water knob and no cold water	
No light in shower	
Water fountain out	

1 <sup>st</sup> urinal out	
Hole in wall between toilet and pipe chase	
Leaking in commode area	
13 lights out throughout zone	
Mold above shower entrance	
Concrete block missing over bed 36	
Hole in wall above bed 36	
Between beds 38 and 39 electrical plate is pulled out	
Bed 42 light outlet uncovered	
Window will not open above bed 46	
Hole in right corner above bed 29	
Vent stopped up in upstairs attic fan	
Urinal 2 and toilet 2 upstairs inoperable	
1 <sup>st</sup> upstairs sink hot water constantly runs	
<b>Unit 29 Bldg. E / Zone B</b>	
No lights above beds 68, 74, 78, 84,98,104,124	
One light out above beds 86, 88, 90, 92, 96, 94, 100, 106, 110, 112 and 116	
Water fountain constantly runs	
1 <sup>st</sup> sink in commode area downstairs will not cut off	
2 <sup>nd</sup> shower downstairs constantly runs	
Screen torn above beds 88 and 119	
Bed 80 has no mattress	
Light fixture missing above bed 92	
Upstairs water fountain inoperable	
Upstairs 1 <sup>st</sup> water faucet not working	
Upstairs 2 <sup>nd</sup> faucet hot water does not cut off	
Upstairs 2 <sup>nd</sup> shower loose from wall	
1 <sup>st</sup> and 2 <sup>nd</sup> sink upstairs need cold water faucet	
Pipe chase open throughout zone	
Upstairs shower has light out	
Attic fan dirty and leaking	
Socket out of wall by bed 97	
<b>Unit 29 Bldg. F / Zone A</b>	
Light out over beds 2, 22,18,26,	
One light out over bed 20,	
Light missing over beds 14,16,24 and 28	
Missing cover plates for exposed wires above bed 14	
Downstairs shower 2 <sup>nd</sup> sink has no faucet head	
2 <sup>nd</sup> commode is out of order	(See Photo Page 29)
Pipe chase unlocked throughout building	
Metal fabrication has been pulled back	(See Photo Page 30)
Bed 27 has missing light cover	

Hole in wall above bed 34	
Bed 32 window will not open	
Paint stored in pipe chase	(See Photo Page 39)
Ceiling metal torn between beds 29 and 64	(See Photo Page 33)
Upstairs 1 <sup>st</sup> shower inoperable	
Upstairs 1 <sup>st</sup> and 2 <sup>nd</sup> sink does not work	
Upstairs shower lights out	
Bottom of water fountain is missing cover	
Window is missing glass	(See Photo Page 40)
Upstairs has 1st urinal out of order	(See Photo Page 31)
Wires exposed next to microwave	
Water fountain does not work	
Cell 32 42 and 33 has no light outlet cover	
Beside bed 34 has hole in wall	
Behind bed 31 has hole in wall	
<b>Unit 29 Bldg. F / Zone B</b>	
Outlet burned and has no cover next to zone door	
Above bed 66 has no electrical plate cover	
Water fountain bottom cover missing and water fountain does not work	
Hole in ceiling next to shower downstairs	
17 lights out throughout building	
Bird nest in several windows throughout zone	
<b>Metal torn down between CTQ 5 and CTQ 6</b>	
Hole in ceiling between bed 118 and 119	
Upstairs 1 <sup>st</sup> lavatory sink is missing knobs and 2 <sup>nd</sup> sink is stopped up	(See Photo Page 32)
Upstairs commode 1st and 2 <sup>nd</sup> are out of order	
Upstairs sink has no knob and commode is out of order	
Screen torn above bed 72	
Upstairs has two urinals out	
Upstairs first and second sink inoperable	
Bed 74 has standing water on floor due to leak in cell	
Exposed wired above bed 77	
Blower does not work	
<b>Deficiency</b>	<b>Attachments</b>
<b>Division 2 Unit 29</b>	
Garbage pile up in front of G and H building gate	(See Photo Page 49)
Window in zone door is shattered	(See Photo Page 45)
<b>Unit 29 Bldg. G / Zone A</b>	
Cell 18 low water pressure	
Cell 16 Bed 32-Need mattress and pillow	
Cell 15 window will not open	

Bed 29 needs mattress, pillow, sheets	
Bed 22 needs mattress, pillow	
Bed 21 needs mattress, pillow	
Bed 70 needs sheets	
Bed 69 needs pillow	
Cell 20 hole in window screen, rusty sheets	
Beds 39/40 no cold water in cell	
Bed 43 rusty sheets	
Bed 47 no mattress, no pillow	
Cell 25 water pressure too high, hole in screen	
Cell 26 Bed 51 & 52 no pillow	
Cell 27 Bed 54 no pillow, water pressure low	
Cell 28 Bed 55 no pillow	
Cell 29 need mattress, no pillows, rusty sheets, hole in window	
<b>Unit 29 Bldg. G / Zone B</b>	
Roaches on the floor near shower area	(See Photo Page 47)
Downstairs shower 3 light is out	
Light out between cells 16 and 17	
Cells 8 and 11 window needs cleaning	
Cell 11,12, 6,3 and 4 leaks in cell	
Cell 9 water leaks in cell	(See Photo Page 36)
Cell 5 ceiling has a leak	(See Photo Page 37)
Cell 2 water constantly runs	
Cell 1 has no cold water button	
Cell 39 has no hot water	
Cell 32 has low water pressure	
Cell 34 lavatory sink is stopped up and water runs continuously	(See Photo Page 42)
Cell 71 ceiling has a hole and leaks water	(See Photo Page 43)
Upstairs shower 2 constantly runs and light is out	
Shower 1 has no light fixture	(See Photo Page 46)
Panel cover missing over cell 26	(See Photo Page 48)
Bed 120 has no mattress cover	
Concrete blocks missing from top of the wall	(See Photo Page 41)
No hot water in cell 14 and ceiling leaks down wall	(See Photo Page 34)
Window screens need cleaning throughout building	
Bed 22 has hole in wall on left side	
Bed 123 has no locker box	
Cell 27 has hole in wall and has no panel above cell door	
Cell 29 has two holes in wall on left side and window will not close	(See Photo Page 35)
<b>Unit 29 Bldg. H / Zone A</b>	
Cell 19 has a hole in the ceiling, leaks water	

when it rains	
Bed 37&38 needs a pillow	
Bed 31&32 needs a pillow and mattress	
Cell 14 Bed 28 needs a mattress, water pressure is low, lights don't work, sockets don't work	
Cell 40 Bed 79 needs a mattress, pillow, sockets don't work	
Cell 20 no mattress cover	
Cell 21 hole in screen, no mattress	
Cell 22 no pillow	
Cell 23 Bed 45 no mattress, no pillow	
Cell 27, 29 hole in screen	
Showers 1 & 3 no lights	
Cell 32 hole in screen, no mattress cover	
Cell 35 no mattress cover	
Cell 37 no mattress cover, no pillow	
<b>Unit 29 Bldg. H / Zone B</b>	
Downstairs shower 2 has no lights	
Shower 3 light is out, water constantly runs and has garbage can and water cooler inside	
Cell 19 light cover plate missing and has no mattress	
Cell 16 window missing	
Cell 13 window leaks	
Cell 11 has hole in wall and leaks inside cell	
Cell 17 Light cover plate missing, no mattress	
Bed 109 has no mattress cover	
Bed 82 needs matter cover	
8 lights out throughout zone	
Cell 19 water runs constantly	
Cell 20 has no hot water	
Bed 119 has no mattress cover	
Cell 21 has no lights, no hot water and no mattress cover	
Bed 131 has no mattress	
Cell 27 hot water button sticks on sink	
Cell 28 sink has leak and hot water button sticks on sink	
Cell 31 has wire attached to light switch	
Cell 32 has no power, hole in wall and no light switch cover	(See Photo Page 51)
Cell 35 and 37 has exposed wires	(See Photo Page 52)
<b>Unit 29 Bldg. I</b>	
Drink cooler from breakfast feeding sitting outside	
Water is leaking from ceiling inside the building	(See Photo Page 53)
Ceiling has a hole above the circuit room	(See Photo Page 54)

<b>Unit 29 Bldg. I / Zone A</b>	
Water leaking from ceiling by the entrance to A-Zone sally port door	
Cell 18 Bed 36 needs a mattress	
Cell 16 Bed 32 needs a mattress, pillow, has a hole in the screen	
Cell 15 has a hole in the window screen	
Cell 12 hot water knob in sticking	
Cell 11 window has a thick rust on it	
Cell 22 torn mattress, no pillow	
Cell 23 no pillow	
Cell 24 bed 47 no mattress	
Cell 26 bed 51 no mattress	
Cell 28 bed 55 no mattress	
Showers water too hot, lights out	
Cell 35 window will not close	
Cell 37 bed 74 no mattress	
Cell 40 bed 79 no mattress	
<b>Unit 29 Bldg. I / Zone B</b>	
Hole in ceiling about circuit room leading to B-Zone	
Rains in cells 18 and 12 through the window	
Cell 13 window leaks	
Downstairs showers 2 and 3 has lights not working	
Downstairs shower 2 inoperable	
Rains in cell 17 and water runs constantly in sink	
Cell 15 and 16 leaks	
Cell 12 has lights not working	
Cell 11 window out	
Cell 1 has no hot water and no power	
Cell 2 need mattress	
Cell 6 has no light fixture	
Cells Light fixture covers missing throughout building	
Cell 5 has lights not working	
Five lights out throughout zone	
Bed 119 needs mattress cover	
Cells 24, 27, 33 and 39 has no cold water	
Bed 142, 154, 153 has no mattress cover	
<b>Unit 29 Bldg. J / Zone A</b>	
Zone Closed	
<b>Unit 29 Bldg. J / Zone B</b>	
Cell 19 commode button leaks	
Cell 7 commode doesn't flush	
<b>Unit 29 Bldg. K</b>	

Bird nest above entrance door and bird droppings at the door	(See Photo Page 55)	
<b>Unit 29 Bldg. K / Zone A</b>		
Shower 3 constantly running		
Cell 2 electrical socket is out of order		
Cell 3 toilet is leaking		
Cell 4 no power, sink out of order		
Cell 9 toilet is leaking		
Exhaust fans are not working on the zone		
Top tier shower no lights		
Cell 20 torn mattress, no cold water		
Cell 22, 23, 23, 32, 29, 32, 36, 37, 38 no pillows		
Cell 20 and 29 torn mattresses		
Cell 33 and 34 no mattresses		
<b>Unit 29 Bldg. K / Zone B</b>		
Downstairs showers 1 and 3 has no light fixture		
Cell 18 toilet not working		
Water coming from pipe chase between cells 18 and 19 and roaches crawling up the wall		
Cell 16 has no lights, leaks inside, sink will not cut off and has no cold water		
Cell 11 and 32 has no cold water		
Cell 1 no mattress		
Cell 7, 11 and 16 no light cover		
Bed 90 no mattress cover		
Bed 92 no mattress		
12 lights out throughout building		
Bed 127 no mattress		
Cell 25 window will not open		
Cell 26 has no cold water		
Top cover missing over cells 27 and 28		
Upstairs showers 1, 2 and 3 has no lights		
Cell 38 toilet and sink does not work and hole inside window		
Cell 31, 33, 37 has no hot water		
Cell 7 has roaches crawling on wall		
<b>Unit 29 Bldg. L / Zone A</b>		
Shower 3 upstairs is out of order		
Cell 12 no hot water, knob is sticking		
Cell 10 no pillow		
Cell 20 no mattress cover, hole in screen		
Cell 24 no pillow		
Cell 25 no mattress cover		
Cell 27 hole in screen		
Cell 28 no mattress		
Cell 30 no mattress cover		

Showers 1 & 3 no lights	
Cell 32 no mattress, hole in screen	
Cell 33 no mattress cover	
<b>Unit 29 Bldg. L / Zone B</b>	
Showers 1 and 3 has no light	
Cell 17 has no cold water	
Cell 25 and 26 window leaks from bottom	
<b>UNIT 29 Kitchen</b>	
Garbage pile up in front of kitchen gate by control room area	
Ice machine drain pipe leaking	
Paint has to be removed from above steam tables on all serving lines	
Serving lines 1 and 2 ice machines leaking under bottom	
<b>Unit 29 Gym</b>	
Birds present in gym	
Behind and inside of warmer was dirty	
Bag of eggs inside clean food tray	
Pop bottle inside clean food trays	
Offender urinal does not flush	
Receptacle cover missing on east wall in offender bathroom exposing wires	
Socket does not work in offender bathroom	
Ceiling falling in offender bathroom	(See Photo Page 50)
Offender drinking cups on counter in barbershop	
Serving spoons were inside of milk crate on counter in barbershop	
Cleaning towels inside water without sanitizer	
No paper towel in dispenser about hand wash sink	
Roach crawling on barbershop counter	
Barbershop janitorial supply room drain backed up and filled with food inside	(See Photo Page 38)

**Area II**  
**(Units 25, 26A-B & Kitchen, 28, 30A-D, 30 Gym, Education, 31, 42)**

Environmental Sanitation	Date of Inspection: June 05-06, 2017
DEFICIENCY	Attachments
<b>MSP Unit #25</b>	
<b>A-zone</b>	
Mop sink constantly running and leaking	
1 <sup>st</sup> , 2 <sup>nd</sup> and 4 <sup>th</sup> commodes are out of order	(See Photo Page 82) (See Photo Page 83)
Sinks 2 and 5 are out of order	
Showers 3, 4 and 5 are out of order	
<b>No water fountain on the zone</b>	
No lights are working in cubicle 7-12 and the windows need screens	
Holes in window screens next to beds 23, 24 and 27, 37 and 38, last cubicle next to beds 53-60	
<b>Exhaust fans are not working</b>	
Exhaust vent covered with dirt	(See Photo Page 84)
Beds 13, 35, 38, 40, 41, 58 no pillows	
<b>B-zone</b>	
Showers 1, 4, 5 and 6-out of order	
Water is leaking behind the shower walls into the 1 <sup>st</sup> cubicle next to beds 61, 62 & 63 causing the pod to flood	
2 <sup>nd</sup> sink no hot water	
Urinal is out of order	
<b>Exhaust fan not working</b>	
Hole in the wall next to the water fountain	
Water fountain is not working	
Beds 13, 35, 38, 38 and 40, 68, 70, 74, 88, 89, 90- No pillows	
Beds 74, 75, 76, 83, 90, 88, 87, 85, 84, 115, 114 torn mattress	
Bed 75-no mattress cover	
No window screens-beds 84, 91 and 103	
<b>C-zone</b>	
Fourteen (14) lights out throughout zone	
Food trays left on the floor at the zone door containing food	
<b>Water fountain will not get cold</b>	
Sink 1 pipe missing	

Urinal out	
Drain covers missing in shower/commode area	
1 <sup>st</sup> shower on right has no handle	
1 <sup>st</sup> and 2 <sup>nd</sup> shower on left has no handle	
Tear in ceiling over shower	
No light cover in shower area	
Mop sink stopped up	
Water from shower leaks between beds 123 & 124	
Beds 144, 174, and 180 had torn mattress	
Bed 135 no mattress	
<b>D-Zone</b>	
Floor fans need cover	
Missing water fountain	
Double pain window missing by beds 210 and 211	
3 <sup>rd</sup> sink missing pipe	
No drain cover in shower floor	
Urinal out	
2 <sup>nd</sup> shower has no handle	
3 <sup>rd</sup> shower has no handle nor shower head	
4 <sup>th</sup> shower has no handle and hole in wall	
4th commode does not flush	
<b>FOOD SERVICE SANITATION-Unit 25 Kitchen</b>	
Offender serving food with no hair net	
Cold food temperature on potato salad 78 degrees be 41 degrees or less	
No working cooler	
Potato salad sitting out beside sink, temperature was 69 degrees and should be 41 degrees or less	
No paper towel dispenser	
Leaking under the sink	
Dishwasher had no sanitizer	
Fan needs cleaning	
Ice machines need cleaning	
Ice scoop broken	
<b>MSP Unit #26 A Building</b>	
<b>A-Zone</b>	
5 <sup>th</sup> shower out of order	
Screen torn next to bed 23	
No screen-bed 53, 55, 56	
Rusty sheets- bed 21, 43	
No lights in cubicle of beds 29, 30 & 33-38	
No pillows-bed 30, 37	

<b>B-Zone</b>	
4 <sup>th</sup> sink is out of order	
4 <sup>th</sup> shower is out of order, hole in wall	
3 <sup>rd</sup> shower continuously running water	
Water fountain is out of order	
Exhaust fan out of order	
No lights-beds 89, 94 & 112	
No pillow-bed 57, 58, 69, 73, 76, 77, 81, 85, 86, 96, 100, 101, 105	
Bed 65, 71, 72, 91, 92 holes in screen	
No sheets-beds 81, 84, 87	
<b>C-Zone</b>	
2 <sup>nd</sup> sink is out of order	
Showers 2 and 6 out of order	
2 <sup>nd</sup> toilet is out of order	
5 <sup>th</sup> sink is out of order	
Water fountain needs a cover	
Window screen is needed next to beds 153, 166,167	
2 sockets are out of order in room with bed 166	
Exhaust fans out of order	
No lights by bed 153,154,167,168	
No window screen by bed 165,166	
Torn mattress-bed 120, 139, 142, 161	
No pillow-bed 120, 124, 126, 129, 134, 140, 142, 145, 149 155	
No mattress cover bed 116	
No mattress bed 129	
<b>D-Zone</b>	
1 <sup>st</sup> urinal out of order	
4 <sup>th</sup> shower out of order	
Hole in wall next to the water fountain	
Water fountain is out of order	
Exhaust fans are out of order	
Water leaks in the 1 <sup>st</sup> pod when the shower is on	
Rusty sheets-bed 221	
Holes in screen-bed 210, 215	
No pillows-bed 176, 179, 183, 184, 209, 217	
Torn mattress-bed 184	
<b>E-Zone</b>	
Middle sink inoperable in commode area	
Ceiling falling in commode area	
Mold present in shower area	(See Photo Page 69)
Lights out in shower	
Water leaks from shower into hallway	

Laundry Room has water leaking on floor through the wall	
Ceiling falling in laundry room	
<b>MSP Unit #26 B Building</b>	
<b>Zone-A</b>	
Urinal 1 and 2 inoperable	(See Photo Page 65)
Offender milk in sink	
Mold behind wall in shower area, the wall and floor tiles are torn and 3 <sup>rd</sup> shower is missing shower head	(See Photo Page 67)
Second left shower and second right shower inoperable	
One light out over bed ten	
Bed #4 bird nests in the window	(See Photo Page 66)
Bed 10 has torn mattress	
<b>Zone-B</b>	
2 <sup>nd</sup> commode is out of order	(See Photo Page 68)
4 <sup>th</sup> sink inoperable	
5 <sup>th</sup> sink has no cold water	
3 <sup>rd</sup> commode and Second urinal inoperable	
Dirty curtains hanging in shower area	
No water fountain	
First shower inoperable	
2 <sup>nd</sup> shower inoperable and needs shower head	
<b>Zone-C</b>	
1st & 6 <sup>th</sup> shower knobs are missing	
1 <sup>st</sup> urinal is out of order	
Water fountain water pressure is low	
Torn mattresses-bed 111, 115, 159	
No pillows- beds 109, 128, 126, 138, 139, 141, 142, 146, 150	
Holes in window screens- beds 160, 161, 155, 154, 149, 148, 147	
<b>Zone-D</b>	
Holes in the walls by the showers	
<b>Zone-E</b>	
Water in sink too hot (131 degrees)	
Shower one has missing shower head	
<b>Unit 26 Kitchen-FOOD SERVICE SANITATION</b>	
No paper towel in dispenser at hand wash sink	
No paper towel in bathroom	
Broken handle on left oven	
Open and unopened salad dressing stored in cooler temperature was 80 degrees and should	

be 41 degrees or less	
Ranch salad dressing container contained sugar	
Bread stored without a date	
Open and inedible mayo stored inside Ranch dressing container	
Lemon Juice Concentrate stored in cooler with an expiration date of 3/03/16	
Cooler with a (not in use label on the outside of cooler) being used for storage and contained rust throughout	
Oven vent needs filter	
Storage room cooler contained personal drinks bottles	
Storage room contained food without a date	
Ceiling tile missing in storage room	
Sample tray was being stored in cooler instead of freezer	
Dish room contained unclean trays in wash area	
Large trays were improperly stored (holding water)	
<b>Unit 26 Barber Shop</b>	
No paper towel in dispenser	
No hot water in neither sink	
Sink by door has slow drain	
<b>UNIT 28</b>	
<b>Zone A</b>	
Shower missing tiles	
No water fountain on the zone	
Bed 46 pillow is torn	
Bed 47,48 holes in screen, light bulbs needed	
Bed 39 mattress is torn	
<b>Zone B</b>	
Bed 68 needs a pillow	
Room 57-62 window screen is torn	
Bed 50 mattress is torn	
Room 13 holes in screens by bed 58	
<b>Zone C</b>	
Water fountain is out of order	
Exhaust fan doesn't work	
Bed 120, room 26-needs mattress	
Bed 126, room 27-needs a pillow	
Room 30-lightbulb replacement is needed	
Room 30-hole in window screen	
Bed 143-rusty sheets	
Bed 126-No pillow	
Room 29-bed 139 mattress is torn,	

Room 29 bed 139 hole in screen	
<b>Zone D</b>	
No water fountain on the zone	
Beds 174, 175 and 176-no pillow	
Room 32-hole in screen	
Bed 150 mattress is torn	
<b>MSP Unit #30 A Building</b>	
Trash in front of building on ground with trash bins present	
Front entrance contains food trays with food remains	
<b>Zone A</b>	
Six(6) dayroom lights out	
Commode 2 & 5 not working	
Urinal 2 out of order	
Spider webs located throughout building	
Sink #8 not working	
Showers 4 and 5 need shower heads	
Bed 17 has torn mattress	
Mop sink has improper handle	
Exhaust fans needs cleaning	
Vent cover needs replacing over beds 13 and 14	
Beds 78, 36 need mattress	
Beds 91, 49, 97 need mattress cover	
Beds 98, 50,52,58,59,57 mattress torn	
Beds 99, 103, 42 has rusty sheets	
<b>Zone B</b>	
Spider webs located throughout ceilings	
Light out over bed 14	
Spider webs and light cover missing over beds 169 and 171	
Water fountain run constantly	
Ceiling falling in shower	
5 <sup>th</sup> shower missing shower head	
Shower drain has no cover	
4 <sup>th</sup> stall has no commode	
Water temperature in sink too hot (125 degrees)	
Wall socket loose	
1 <sup>st</sup> urinal missing	
8 <sup>th</sup> sink cold water not working	
2 <sup>nd</sup> shower knob missing	
Beds 111, 113, 127,133,146,172, 174 has rusty sheets	
Beds 134, 152, 180, 211 needs mattress	
Beds 187, 169, 180, has torn mattress	
Bed 187 needs sheets	

<b>MSP Unit #30 B Building</b>	
<b>A-Zone</b>	
2 <sup>nd</sup> and 3 <sup>rd</sup> lavatory sinks are missing pipes	(See Photo Page 86)
5 <sup>th</sup> toilet is out of order	
Water fountain is out of order	
2 <sup>nd</sup> and 3 <sup>rd</sup> showers are missing knobs	(See Photo Page 85 & 87)
<b>B-Zone</b>	
Sinks 4 and 5 are inoperable	
Toilets 2,3,4 and 6 are inoperable	
3rd urinal is out of order	(See Photo Page 80)
1 <sup>st</sup> and 2 <sup>nd</sup> urinals are out of order	(See Photo Page 81)
Showers 1,2,4, and 6 are inoperable	
Beds 1,2,3,5,7,11,13,16,19,21,23, 55, 62, 77,75,100, 101, 124, 128, 131, 137, 145, 148 have torn mattresses	
Beds 197, 198, 193, 194, 191, 192, 213, 209, 211, 207, 203 and 204 have missing pillows	
<b>MSP Unit #30 C Building</b>	
<b>A-Zone</b>	
Fourteen (14) lights out throughout building	
Need high cleaning for dust and spider webs	
No water fountain	
Shower #1 has no handle	
Shower #2 has no handle and water runs constantly	
Showers 3, 5 and 6 has no handle on shower	
Sink 3 and 5 inoperable	
Two (2) lights out in commode unit	
Four (4) commodes not working	
3 <sup>rd</sup> commode has burn residue	
6 <sup>th</sup> commode does not work	
Urinal 3 and 4 does not work	
Knob on urinal 4 need replacing	
Beds 34, 99, and 104 need mattress	
Bed 4 need mattress cover	
Bed 3, 43, 57, 59, 73 has torn mattress	
Bed 63 has torn pillow	
<b>B-Zone</b>	
Thirteen (13) lights out throughout zone	
No lights over bed 215 and 216	
Shower #4 has no hot water handle	
Shower #5 has no handles	
High and low cleaning needed throughout zone for dust and spider webs	
Toilet #6 does not work	
Roaches in commode area	

Milk crates located in commode area	
<b>MSP Unit #30 D Building</b>	
<b>A-Zone</b>	
Sink 2 and 5 is out of order	
Water fountain needs a cover	
1 <sup>st</sup> toilet is out of order	
3 <sup>rd</sup> urinal is out of order	
Showers 1, 2 and 4 are missing the knobs	(See Photo Page 88)
Beds 50, 52, 46, 37, 28, 54, 49, 60, 61, 68, 82 no mattress	
Beds 2 and 16-rusty Sheets	
Bed 13, 86 needs mattress cover	
Bed 54-no pillow	
Bed 76-no sheets	
Exhaust fans not working and needs cleaning	
<b>B-Zone</b>	
Commode is missing from the floor	(See Photo Page 89)
Sink #1 is out of order	
No mattress-Beds 164, 174, 180, 182, 185, 124	
No mattress cover-Beds 174, 176, 187, 196, 203	
Torn mattress-111, 125, 147, 160	
No pillows-165, 197, 201, 202, 209	
Rusty sheet- bed 178	
<b>FOOD SERVICE SANITATION-30 Kitchen</b>	
Standing water in front of U/30 kitchen	
No hot water in sink by security office	
Flies in serving line area near steam tables	
Oven needs cleaning	
Dining Hall #1- Trays not properly cleaned with food waste still on them	
Light fixtures needs cleaning throughout	
Supply Room- Rat droppings on shelves	
No hot water in inmate bathroom and kitchen	
Dishwashing room-Dishwasher not getting up to correct heating temperature of 180 degrees	
<b>Pots and Pan room- Standing water on floor</b>	
Pipe Burst without known source of location	
Unclean dishes containing food particles	
Hole in the wall	
Tray racks dirty	
Evidence of paper burning in corner of kitchen floor	
Roaches crawling on tray racks	
Drain stopped up in between freezer/cooler #2	
Freezer #2- food stored without date or labels	

Standing water in front of freezer #2	
Outside Dining Hall (Back dock)- Food tray rack contained bird droppings	
Outside freezer food has no date	
Drain not working containing stagnated water	
Trash in and around drain (drain could cause contamination if water gets in cooler)	
Loading dock area-drain containing standing water	
Crack in back wall of dish room	
Warehouse #1 – no date on pancake waffle mix	
Drinking dispensers left outside containing left over coffee	
Warehouse #2- rains inside of building	
Food was stored on floor	
Bugs on butter inside cooler	
Red Pack Sweet Potatoes had no date	
Cooler contained raw and ready-to-serve food stored together on same side	
Leak inside of cooler	
No thermometer inside building	
<b>MSP Unit #30 ABE</b>	
Wasn't able to inspect due to door being locked	
<b>MSP Unit #30 A&amp;D School</b>	
1 <sup>st</sup> urinal out of order	
6 <sup>th</sup> urinal is missing	
2 <sup>nd</sup> sink is out of order	
Trash on ground containing vermin	
<b>MSP Unit #30 Gym</b>	
Two lights out	
No hot water in staff bathroom	
No paper towel in barbershop	
No hot water in barbershop	
Sink #2 inoperable, no hot water and floor leaks in offender restroom	
<b>MSP Unit #31</b>	
<b>A-Zone</b>	
4 <sup>th</sup> shower is out of order	
Room 121-no pillow	
<b>C-Zone</b>	
3 <sup>rd</sup> shower is out of order	
Room 149-no pillow	
Room 147-no pillow	
<b>D-Zone</b>	
Room 39, 8 and 9 needs a pillow	
Room 42, needs a pillow	

<b>MSP Unit #31 Food Sanitation</b>	
Hand wash sink has no paper towel	
Cracker Barrel Mint Box contained razors stored by serving dishes	
<b>MSP Unit #42 - Hospital</b>	
<b>Kitchen</b>	
No soap in kitchen	
No paper towel in soap dispenser	
Large trays were improperly stored and contained standing water	
Offender milk stored in ice machine	(See Photo Page 71)
Hand wash sink has slow drain	
No sanitizer in dishwasher	
Cooler with 65 degrees temperature has salad dressing and mustard stored inside and should be 41 degrees or less	
No sanitizer for three compartment sink	
No soap in offender bathroom	
Trash stored near kitchen door	
Six missing light covers	
Three compartment sink constantly runs water	
Pallets stored behind kitchen	
Biohazard chemical storage key is broken in the lock	
<b>Westward</b>	
Room 219 hole in the wall next to bed A	
<b>Southward</b>	
Room 202 and 204 lights are out of order	
<b>Eastward</b>	
All call lights are blinking	
Sink knobs are missing out the bathroom	

## (Unit 32 Central Laundry, Vo-Tech Kitchen)

Environmental Sanitation	Date of Inspection: June 08, 2017
Deficiency	Attachments
<b>MSP Unit #32-Laundry</b>	
All urinals out of order	
Washers #71493 and 71496 are out of order	
Washer #71495 will not complete wash cycle	
Washer #71497 leaks water from underneath	(See Photo Page 70)
Handles on doors does not seal door properly	
Dryers #1, 2, 6, 8, and 10 are inoperable	
<b>Vocational School</b>	
Three sink hot water temperature too hot (136 degrees)	
Mixing bowl has dead bugs in it	(See Photo Page 72)
Sporks improperly stored; must have handle facing up at all times	
Personal food items stored in cooler with unprepared food	
Wood stored inside sugar and flour bins	
High and low cleaning needed throughout ceiling	
<b>Processing Kitchen</b>	
Temporarily Closed- Per Agriculture Director Mr. Roger Davis	
<b>Cold Storage</b>	
Brick loose near back door	(See Photo Page 57)
Food trays stored outside and birds have began to nest in them	(See Photo Page 56)
Ceiling is falling down	
<b>Metal Fab Building</b>	
Two propane and two cookers stored in front of kitchen	(See Photo Page 64)
No hand soap in kitchen	
Mice droppings throughout building including serving lines, cleaning cart, serving pans and warmers	(See Photo Page 60) (See Photo Page 62)
Dirty food containers stored in front of metal fab kitchen	(See Photo Page 58)
Dead mice inside food warmer	(See Photo Page 59)
Staff bathroom not flushing	
Mice droppings behind dish rack in metal fab kitchen	(See Photo Page 61)
Bread, mustard, and empty bucket located inside drink cooler	
Cleaning cart in kitchen had mice droppings on it	(See Photo Page 63)

Food stored inside inoperable cooler	
Dirt build up behind warmer	
No soap located in offender bathroom	
No light in offender bathroom	
Ice machine needs cleaning	



**Unit 29D Zone B – 2<sup>nd</sup> urinal is out of order**



**Unit 29D, B-Zone Bird Nest in Window**



**Unit 29D, B-Zone Hole in the Window Screen**



**Unit 29D, B-Zone Roaches Crawling on the Floor**



**Unit 29E, A-Zone Ceiling Frame is Broken**



**Unit 29E, A-Zone Pipe Chase cover is missing**



**Unit 29F, A-Zone 1<sup>st</sup> commode is out of order**



**Unit 29F, A-Zone Metal Fabrication has been pulled back**



**Unit 29F, A-Zone 1<sup>st</sup> Urinal is out of order**



**Unit 29F, B-Zone 1<sup>st</sup> Lavatory sink is missing knobs and 2<sup>nd</sup> sink is stopped up**



**Unit 29F, B-Zone Metal Fabrication is torn**



**Unit 29G, B-Zone Cell #14 – water leaks from the cell into the Corridor**



**Unit 29G, B-Zone, Cell #29 – cell wall has a hole in it**



**Unit 29G, B-Zone Cell #5 ceiling has a leak**

36

35



**Unit 29G, B-Zone Cell #5 ceiling has a leak**



**Unit 29, Barbershop closest has spaghetti in the drain**



**Unit 29D, Birds are nesting above the entrance door**



**Unit 29F, A-Zone Pipe Chase unsecured**



**Unit 29F, Window is missing glass**



**Unit 29G, B-Zone Concrete blocks are missing from the top wall**



**Unit 29G, B-Zone Cell #34 lavatory sink is stopped up and water runs continuously**



**Unit 29G, B-Zone Cell #71 ceiling has a hole and leaks water**



**Unit 29D, B-Zone shower has mold in the ceiling**



**Unit 29G, Window in zone door is shattered**



**Unit 29G B-Zone 1<sup>st</sup> shower has no light  
46**



**Unit 29G, B-Zone Roaches crawling up the wall**



**Unit 29G, B-Zone Panel cover is missing above the cell doors**



**Unit 29, Buildings G/H has Garbage piled up at gate**



**GYM bathroom ceiling is falling down**



**Unit 29H, B-Zone Cell #32 light does not work**



**Unit 29H, B-Zone cell has exposed wires running from switch box**



**Unit 29I, water is leaking from ceiling inside the building**



**Unit 29I, ceiling has a hole above the circuit room**



**Unit 29K, Bird nest above entrance door and bird droppings at the door**



**Cold Storage has food trays stored outside and birds have begun to nest in them**



**Cold Storage wall has loose center blocks**

57

57



**Dirty Containers stored in front of Metal Fab Kitchen**



**Metal Fab Food Warmer with mice droppings and dead mice inside**



**Metal Fab kitchen had mice droppings around serving line**



**Metal Fab kitchen had mice droppings behind dish rack**



**Metal Fab kitchen had mice droppings inside serving pans**



**Metal Fab kitchen had mice droppings on the cleaning cart**



**Metal Fab kitchen had two (2) propane tanks and a dirty deep fryer stored in front of the kitchen**



**Unit 26B A-Zone, 1<sup>st</sup> and 2<sup>nd</sup> urinals are out of order**



**Unit 26B A-Zone Bed #4 has a bird nest inside the window**



**Unit 26B A-Zone, 3<sup>rd</sup> shower head is missing, wall and floor tiles are torn**



**Unit 26B B-Zone, 2<sup>nd</sup> commode is out of order**



**Unit 26E A-Zone, shower has mold and mildew**



**Unit 32 (Laundry) 2<sup>nd</sup> machine leaks water from underneath**



**Unit 42 (Hospital) Kitchen milk was stored inside the ice machine**



**Vo-tech Kitchen mixing bowl has dead bugs in it**



**Unit 29A Zone A, Cell #15 has hole in the screen and the light is out**



**Unit 29B has exposed wires in the ceiling**



**Unit 29B Ceiling has exposed wires and light is out**

75

75



**Unit 29B ceiling has exposed wires**



**Unit 29B water leaks through the wall**



**Unit 29C Zone B, Bed #94 – Bird nest inside the window and holes in the screens**



**Unit 29A Zone A has lights out throughout the zone**



**Unit 30 Bldg. B, 1<sup>st</sup> urinal is out of order**



**Unit 30 Bldg. B 1<sup>st</sup> and 2<sup>nd</sup> commodes are out of order**



**Unit 25 A- 1<sup>st</sup> and 2<sup>nd</sup> commodes are out of order**



**Unit 25 A- 4th commode is out of order**



**Unit 25 A- Zone A, Exhaust Vent covered with dirt**



**Unit 30 B Zone A, Shower is missing knobs**



**Unit 30B Zone A – 2<sup>nd</sup> and 3<sup>rd</sup> lavatory sinks are missing pipes**



**Unit 30 Zone A, shower is missing knobs**



**Unit 30D Zone A, shower is missing knobs**



**Unit 30D Zone B, commode is missing**